






Energy Recovery, Inc.  
 1908 Doolittle Dr.  
 San Leandro, CA  
 94577, USA  
 Phone: 510-483-7370  
 Fax: 510-483-7371

**PERFORMANCE CURVES  
 PX-45S PRESSURE  
 EXCHANGER**

REV	BY	CKD	REVISION	DATE
000	RLS	RBC	Issued for Distribution	12/1/04
001	JMP	RLS	Revised Mixing Curve	10/6/05

Doc. No.	80040-01
Sheet No.	1 of 1



NOTE: SEE ERI DOCUMENT NUMBER 80008-01 FOR DEFINITIONS AND TEST CONDITIONS