






Energy Recovery, Inc.
 1908 Doolittle Dr.
 San Leandro, CA
 94577, USA
 Phone: 510-483-7370
 Fax: 510-483-7371

**PERFORMANCE CURVES
 PX-140S PRESSURE
 EXCHANGER**

| REV | BY | CKD | REVISION | DATE |
|-----|-----|-----|-------------------------|---------|
| 000 | RLS | RBC | Issued for Distribution | 8/5/04 |
| 001 | RBC | RLS | Revised Mixing Curve | 10/3/05 |
| | | | | |

| | |
|-----------|----------|
| Doc. No. | 80039-01 |
| Sheet No. | 1 of 1 |



NOTE: SEE ERI DOCUMENT NUMBER 80008-01 FOR DEFINITIONS AND TEST CONDITIONS